

## Vehicle List for School Board of Manatee County Auction SBMC13 May 22nd, 2010

ID	Year	Manufactur	Vehicle Info	Capacity	Engine	Transmission	Odometer	VIN	Notes
38	1996	Thomas	Thomas/IHC	78	DT-466	AT-545	174270	1HVBDAAN0TH383418	Replaced
51	1996	Thomas	Thomas/IHC	78	DT-466	AT-545	166802	1HVBDAAN8TH383411	Replaced
53	1996	Thomas	Thomas/IHC	78	DT-466	AT-545	137695	1HVBDAAN6TH383410	Replaced
95	2000	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	130103	1T7HT4B27Y1081426	Trans/ECM
139	1996	Thomas	Thomas/IHC	78	DT-466	AT-545	183068	1HVBDAAN0TH383404	Replaced
145	1996	Thomas	Thomas/IHC	78	DT-466	AT-545	134712	1HVBDAAN7TH383416	Replaced
147	1996	Thomas	Thomas/IHC	78	DT-466	AT-545	176705	1HVBDAAN2TH383405	Replaced
150	1996	Thomas	Thomas/IHC	78	DT-466	AT-545	142058	1HVBDAAN4TH383406	Oil Leak/Several Lights Out
151	1996	Thomas	Thomas/IHC	W/C	DT-466	AT-545	153483	1HVBDAAN8TH382498	Replaced
152	1996	Thomas	Thomas/IHC	W/C	DT-466	AT-545	130134	1HVBDAAN5TH382961	Replaced/Broken Windshield
153	1997	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	172458	1T7HT4B27V1143998	Replaced
154	1997	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	136454	1T7HT4B29V1143999	Replaced/1 broken Mirror
155	1997	Thomas	Thomas/IHC	W/C	DT-466	AT-545	169188	1HVBDAAN7VH475063	Replaced
157	1997	Thomas	Thomas/IHC	W/C	DT-466	AT-545	133121	1HVBDAAN9VH475064	Replaced
158	1997	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	175519	1T7HT4B29V1154601	Replaced
159	1997	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	171144	1T7HT4B20V1154602	Replaced/Broken Windshield
160	1997	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	171708	1T7HT4B22V1154603	Replaced
164	1997	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	113122	1T7HT4B26V1154605	Replaced
175	1997	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	138502	1T7HT4B2XV1154607	Light Monitor Bad/1 Mirror Broken
184	1997	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	143705	1T7HT4B21V1154608	Replaced/1 broken Mirror
185	1997	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	152298	1T7HT4B23V1154609	Replaced
188	1997	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	147607	1T7HT4B2XV1154610	Needs Fan Clutch
193	1997	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	141684	1T7HT4B21V1154611	Needs Cam Shaft
194	1997	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	176419	1T7HT4B23V1154612	Replaced
195	1997	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	186217	1T7HT4B25V1154613	Replaced
196	1997	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	205843	1T7HT4B27V1154614	Replaced/2 Mirrors Broken
199	1999	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	139428	1T7HT4B23X1166486	ECM/Broken Windshield
203	1999	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	129037	1T7HT4B27X1166488	Replaced
240	1998	Thomas	Thomas/IHC	W/C	T-444E	AT-545	152857	1HVBDAABNXWH580289	Replaced
241	1998	Thomas	Thomas/IHC	W/C	T-444E	AT-545	146309	1HVBDAABN6WH580290	Replaced
242	1998	Thomas	Thomas/IHC	W/C	T-444E	AT-545	131944	1HVBDAABN8WH580291	Replaced
243	1998	Thomas	Thomas/IHC	W/C	T-444E	AT-545	208208	1HVBDAABNXWH580292	Oil Consumption
246	2000	Thomas	Thomas MVP RE	84	CAT3126	MD-3060	177065	1T7HT4B26Y1081434	ECM
441	1984	Blue Bird	Bluebird/IHC	65	6.9	AT-545	84586	1HVLNHGN7EHA61012	Age/Roof A/C & Generator
308	1994	Buick	Buick Century		3.1		62879	1G4AG55M8R6508814	Age
862	2006	Ford	Ford Cargo Van	1 Ton	5.4		18441	1FTSS34L46DB18062	Totaled
168740	1994	Ford	Crown Victoria P71		4.6		74546	2FALP71W8RX182006	Brakes
201754	2003	Ford	Crown Victoria P71		4.6		92153	2FALP71W73X137935	Engine

All information deemed accurate at the time of posting. Subject to verification, correction, additions and/or deletion:

No warranties expressed or implied on vehicles or information supplied